

COMMERCIAL SERVICES

CASE STUDY

Fitness 1440 San Antonio, Texas

FITNESS1440

Miracle Method Refinishes 2,500 square feet of tile floors in locker rooms, saunas and showers.



BEFORE



BEFORE



AFTER



AFTER

The Problem

Tile floors and walls in the fitness center were outdated, damaged, and dirty. Large laminate vanities with sinks, tile showers and saunas were completely covered in soap scum, mold and mildew.

The Miracle Method Solution

The Facility Manager was looking for an affordable renovation solution to address the repair and the appearance needs of Fitness 1440 locker rooms. Miracle Method's Refinishing process delivered faster results than extensive replacement options. The project was completed in just fifteen days with three Miracle Method technicians working around other contractors.

The Process

Miracle Method repaired and refinished the tile floors and walls in gym locker rooms, three saunas and two community showers using our Natural Accents® stone-look finish.



The refinishing process gave the outdated tile a new updated look, offering durability and ease of future maintenance. Grout lines were permanently sealed to inhibit growth of mold, mildew and water damage.

The Result

Miracle Method provided long-desired upgrades to Fitness 1440 locker rooms with surface refinishing, without costly demolition and replacement. The facility manager was pleased with the beautiful transformation that Miracle Method's Refinishing process provided.

Contact us to schedule an on-site review & quote:

1-888-741-3511

sales@miraclemethod.com

View more case studies and examples at:
www.miraclemethod.com/commercial