

The Nation's Largest Surface Refinisher • 135+ Locations

COMMERCIAL SERVICES CASE STUDY

# **Comcast Headquarters Office Building, Denver, CO**

COMCAST

Molecular

Adhesion

Insured and

Warranted

# Miracle Method Refinishes Tile in 28 Restrooms In Comcast Denver Headquarters



▲ Damaged tile walls and floors were repaired and refinished at a fraction of the cost and time for replacement!

## The Problem

Comcast Denver planned a renovation of their headquarters building but wanted to do so with minimal disruption to employees and work. Included in the plan was an update of 28 restrooms, but removing and replacing tile in large bathrooms would mean taking each restroom out of service for two weeks.

## The Miracle Method Solution

Looking for a way to update the bathrooms while minimizing downtime, the building facility manager turned to Miracle Method Surface Refinishing. A plan was established for Miracle Method to refinish floor and wall tile in two of four bathrooms per floor starting Thursday evenings and returning the rooms to service Monday mornings. Work would be done on two floors each weekend until completed.

#### The Process

Miracle Method technicians did prep work, cleaned and made repairs on Thursday evenings then refinished the walls on Fridays. On Saturdays, they refinished the floors, and applied clear coat. Masking was taken down late Sunday and the bathrooms were returned to service on Monday morning. Natural Accents <sup>®</sup> two-tone, stone look finishes and satin clear coat were applied throughout the job for their water resistance, updated look, easy of cleaning and durability.

#### The Results

The Miracle Method Difference, Makes All

the Difference

Employees

Önĺv

Proven

Process

The project was completed over eight weekends, allowing Comcast to maintain their operation without the disruption demolition and tile replacement would have caused. Comcast employees were very impressed with the new look, and Facility Management was impressed with the savings to both budget and time. The refinished surfaces have proven to be easier to maintain than the original tile and grout.

Contact us to schedule an on-site review & quote: 1-888-741-3511 sales@miraclemethod.com

View more case studies and examples at: www.miraclemethod.com/commercial