

COMMERCIAL SERVICES

CASE STUDY

## Fairfield Inn and Suites by Marriott, Findlay, Ohio

### Miracle Method Provides Durable, Slip-Resistant Finish to Improve Bathroom Safety



▲ Bathtubs repaired and refinished to like new. We also applied our technically superior Slip Resistant Surface for increased bathing safety.

#### The Problem

Hotel management at the Fairfield Inn and Suites needed a cost-effective solution to quickly repair and restore 56 bathtubs with failing finishes. In addition, they requested an affordable way to improve bathing safety. The existing bathtubs had been previously refinished by a non-Miracle Method refinisher were peeling, cracking and having caulking issues due to poor cleaning, improper application and the use of acid etching.

#### The Miracle Method Solution

To demonstrate the difference in quality when a tub is properly refinished, Miracle Method refinished one of the hotel bathtubs and included the application of their Slip Resistant Surface (SRS), which was customized to the amount of grip requested by the hotel.

Impressed by the beauty and quality of the refinishing, and the durability of the SRS applied to the bottom of the tub, Miracle Method was selected to repair and refinish the remaining defective bathtubs.



#### The Process

To begin the renovation process, Miracle Method technicians first stripped the failed finish and thoroughly cleaned each of the bathtubs. Miracle Method's proprietary bonding agent, MM4, was then applied to create a molecular bond between the surface and the new finish. Lastly, to satisfy management's request to make the bathrooms safer for hotel guests, Miracle Method's SRS was applied to the bottom of each bathtub.

#### The Results

Miracle Method completed the refinishing project in just seven days, while avoiding extensive replacement costs and disruption to hotel guests. The newly refinished bathtubs were not only beautiful, clean and restored to like-new condition, but the texturized SRS helped reduce slip-and-fall liability. Pleased with the results, Fairfield Inn and Suites continues to utilize Miracle Method for additional refinishing services and bathing safety upgrades.

Contact us to schedule an on-site review & quote:

**1-888-741-3511**

**sales@miraclemethod.com**

View more case studies and examples at:  
**www.miraclemethod.com/commercial**