

Contractor Performance Rating Form

Name of Person Providing Rating and Location of Work: **Richard Watkins, Home Generator Owner, 9140 Kentucky Ave, La Plata, MD 20646**

Description of Work/Job: **Professional installation of a new Generac residential standby generator, including installing a replacement Automatic Transfer Switch.**

Contractor Name: **AmpTech, Inc.** Person Performing the Work/Job: **Frank Boblits**

Date of Work/Job: **1 April 2017**

1. How do you rate the Contractor's availability to perform the work/job?

Very Good Satisfactory Marginal Unsatisfactory

2. How do you rate the Contractor's response time for completing the work in the expected time?

Very Good Satisfactory Marginal Unsatisfactory

3. How do you rate the Contractor's response time to questions and system maintenance questions?

Very Good Satisfactory Marginal Unsatisfactory

4. How do you rate the Contractor's quality of work?

Very Good Satisfactory Marginal Unsatisfactory

5. How do you rate the Contractor's professionalism and curiousness?

Very Good Satisfactory Marginal Unsatisfactory

6. How do you rate the Contractor's overall reliability?

Very Good Satisfactory Marginal Unsatisfactory

Additional Comments:



Signature

18 Apr 2017
Date

Richard Watkins
Name